


Page 1-A

## [Calculating of Ferrite transformers]

For example: we need an HF transformer with these characteristics:



So, again we need to use that famous

Formula:  $\frac{V_1}{N_1} = \frac{I_2}{I_1} = \frac{V_2}{N_2} = \sqrt{\frac{L_1}{L_2}} = \sqrt{\frac{C_1}{C_2}} = \sqrt{\frac{X_{C2}}{X_{C1}}} = \sqrt{\frac{R_1}{R_2}} =$   
 $= \sqrt{\frac{X_{L1}}{X_{L2}}} = \frac{I_1}{I_2}$

in this Application, we need this portion of formula.

we can calculate the  $I_1$ :  $\frac{50}{450} = \frac{5.5}{I_1}$

$$\Rightarrow I_1 = 49.5 \text{ A}$$

So, we should calculate an Inductance of the Primary of transformer, Per 10% of maximum Input current.

10% of 49.5 Amperes = 4.99 Amperes.

$$\Rightarrow X_{L1} = \frac{50 \text{ V}}{4.99 \text{ A}} \approx 10 \Omega$$

and  $X_L = j\omega L \Rightarrow L = \frac{X_L}{j\omega} \Rightarrow L_1 = 1.5 \mu\text{H}$   
 $\sqrt{-1} \times \omega \rightarrow 2\pi \times F$