




Weller WPA 2 repair. Gas would not ignite. Spark was ok. New fuel used. Read below for solution.



The tin cage and the screen should not be outside of the tip. They should remain pressed into the tip.



Here the screen has been inserted into the tin cage.

Each tab is bent slightly outwards. Look close.



Tin cage and screen inserted in tip.

Success! Works every time now! Cheers.

Terry Brown Olds, Alberta, Canada