



Beside JTAG TDO and PDI DATA are sharing the same pin on the device Connector there is a power kick up situation. This can happen when all the following conditions are met:
 - The device uses the internal pull-up on JTAG TDO
 - No start-up delay is used (STARTUPTIME configuration)
 - JTAG is disabled
 Therefore it is possible to disconnect JTAG TDO if necessary



JTAG/PDI Interface



| | |
|--|------------------------|
| Project: Proje Adı? | |
| İstek Adı: İstek Numarası: Sıfır Dahil | |
| Başlık: A3_Navya No: 2 / 5 | Hizalı: 21.17 |
| Tarih: 20.06.2019 | Revizyon: Revizyon No? |
| Hazırlayan: Harekətçisi? | Sematik No? |
| İzahçı: Izahçı? | İzahçı No? |
| Üzüm Ünvanı: Üzüm Ünvanı? | Üzüm Ünvanı No? |
| Kalite: Kalite? | Üzüm Malzeme No? |




1

2

3

4

A



| | | |
|--------------------------|------------------------------------|------------------------|
| Proje: Projenin Adı? | Dosya Adı: SEP_Current_Sink.SchDoc | Hiyerarşî: 2.1.1? |
| Boyut: A3 | Sayfa No: 4 / 5 | Revizyon: Revizyon No? |
| Tarih: 20.06.2019 | | Sematik No: |
| Hazırlayan: Hazırlayan? | | Sematik No? |
| Tasarlayan: Tasarımcı? | | Üst Malzeme No: |
| Tasarım Onay: Onaylayan? | | Üst Malzeme No? |
| Kalite: Kalite? | | |

1

2

3

4

