


Frequency Meter Range:16Hz to 100Hz Sensitivity:0.01Hz - Jumpers



Y. Erol

www.circuit-projects.com