


APPENDIX B: PIC PROGRAMMER



*Other pins of PIC are left not connected