



Require connector to connect a bench power supply like the one used in labs between Vcc and Gnd

Even a single pin jumper at Vcc and gnd will do

Single pin jumper at every IN terminal of TPS2833 IC

A single pin jumper connector at one end of load capacitor C1 to take the output

Arrows are shown where connectors are required