






# Exporting 2D-Field Data



Define a 2D-field monitor.

# Export the Field Data



Select the field plot, and in the post-processing ribbon use the plot data (ASCII)-command to export it.

You can also define the exact step width that should be used.