


Dear Gary

Hi

See below Please:

your Driver



When L_{in} is 1 and H_{in} is 0, $M1$ is OFF and $M2$ is ON (thus G_S of $Q1$ is short circuit) and $M3$ is ON and $M4$ is OFF thus $C1$ will create a loop from $+15$ up to the ground of $15V$ supply. (we connected its ground to the minus supply) so when H_{in} is 1 and L_{in} is 0. what will happen? see Page 2, Please