

Fig 1.Current in the coil with PWM across H1 and H2




Fig 2. Current across Positive terminal with PWM across H1 and H2




Fig 3. Magnified version of figure 2




Fig 3. Magnified view with current on positive terminal and PWM across H1,L1 and H2 respectively hence no shoot through