



### 1. Wave drive :

In wave drive stepping mode only one phase is energized at a time.



### 2. Full Drive :

In full drive, two phases are energized at a time.



### 3. Half Drive :

In half drive, alternately one and two phases are energized. This increases the resolution of the motor.

