



Electrical Diagram



Mechanical Diagram



Winding Instruction

Primary Winding

Start on pin(s) 2 and wind 103 turns (x 1 filar) of item [5]. in 3 layer(s) from left to right. Winding direction is clockwise. At the end of 1st layer, continue to wind the next layer from right to left. At the end of 2nd layer, continue to wind the next layer from left to right. On the final layer, spread the winding evenly across entire bobbin. Finish this winding on pin(s) 1.

Add 3 layers of tape, item [3], for insulation.

Secondary Winding

Start on pin(s) 7 and wind 13 turns (x 2 filar) of item [6]. Spread the winding evenly across entire bobbin. Winding direction is clockwise. Finish this winding on pin(s) 6.

Add 2 layers of tape, item [3], for insulation.

Core Assembly

Assemble and secure core halves. Item [1].

Varnish

Dip varnish uniformly in item [4]. Do not vacuum impregnate.

Comments

- 1. For non margin wound transformers use triple insulated wire for all secondary windings.

Materials

| Item | Description |
|------|---|
| [1] | Core: E20/10/6 (EF20), 3F3, gapped for ALG of 139 nH/T² |
| [2] | Bobbin: Generic, 5 pri. + 5 sec. |

| | |
|-----|--|
| [3] | Barrier Tape: Polyester film [1 mil (25 µm) base thickness], 12.50 mm wide |
| [4] | Varnish |
| [5] | Magnet Wire: 29 AWG, Solderable Double Coated |
| [6] | Triple Insulated Wire: 25 AWG |

Electrical Test Specifications

| <i>Parameter</i> | <i>Condition</i> | <i>Spec</i> |
|---------------------------------------|---|-------------|
| <i>Electrical Strength, VAC</i> | 60 Hz 1 second, from pins 1,2 to pins 6,7. | 3000 |
| <i>Nominal Primary Inductance, µH</i> | Measured at 1 V pk-pk, typical switching frequency, between pin 1 to pin 2, with all other Windings open. | 1664 |
| <i>Tolerance, ±%</i> | Tolerance of Primary Inductance | 12.0 |
| <i>Maximum Primary Leakage, µH</i> | Measured between Pin 1 to Pin 2, with all other Windings shorted. | 49.92 |

Although the design of the software considered safety guidelines, it is the user's responsibility to ensure that the user's power supply design meets all applicable safety requirements of user's product.