


Power supply unit


AC to DC

Primary coils side



E25 transformer
 HD50-E/220-240V
 BS190518 (ROHS)
 HYT0148/A2 E25 (GP)

Lp(3->5) Clockwise winding
 Laux(1->2) Clockwise winding
 Ls1 coil (6->8) Clockwise winding
 Ls2 coil (8->10) Clockwise winding



O1 Vgss(max) = +/-30V
 Vgss(th) 2...4V
 Rds 2...2.5R

O2, O3 - Unusual pinout
 O3 Vbeo(max) = 5V

IC1 Veco(max) 6V

Secondary coils side

