



Work principle :

2 digit in 7segment is view how many plate is around in one minute,example :

If plate is around a sensor 50 times in one minute and then 7segment display number 50

*if speed plate increase, so automatic change also number at 7segment
accustom rotation quantity plate in one minute*

