

NOTES:

This is a multi usage circuit, all parts may not be required for application.
Board can be used for counting and voltage measurement.

Just change program for the correct usage.

D2 is for protection and may not be needed.

Use 16f88 for voltage measurement.

A 16f628A can be used for counting.

Optional 16P Breakout Connector

