



Test circuits for Solid State Relay (SSR)


Before testing check SSR voltage and current max. values




DC in DC load SSR test circuit



DC in AC load SSR test circuit



AC in DC load SSR test circuit



AC in AC load SSR test circuit